

	File Name	Date	Size	DT-X10	DT-X10	DT-X10
		(mm/dd/yy)	(byte)	M30E/ M30U	M30RC/ M30URC	M30RC2/ M30URC2
RF module					Intel	Toyota
OS				4139	4139	4139
SDK						
	Export SDK					
	DT-X10 SDK.msi	03/17/03	28,063,744		Ver.1.00 Released	
	Emulation SDK					
	DT-X10EM SDKFOREVC.msi	04/16/03	46,295,552		Ver.1.00 Released	
Patch						
	Service Pack					
	ServicePackDTX10.CAB	07/11/03	1,714,880		Ver.2.02 Released	
	General Patch					
	PatchDTX10.004.CAB	06/07/04	858,852		2004/06/29 Released	
	PatchDTX10.005.CAB	06/07/05	1,194,665			
	PatchDTX10.007.CAB	08/06/05	1,305,419		Ver.007 Released (2005/8/12)	
	Toyota RF driver Patch					
	wlan-GWCFDTX10.CAB	05/26/05	423,119	Do not need		Ver.1.00 Released (2005/8/12)
	Wireless LAN improvement Patch					
	netuiDTX10.CAB	08/27/04	160,678	Do not need	Ver.1.03 Released	Do not need
	ActiveSync improvement Patch					
	BirdaDTX10&DT870&DT500&DT5100.CAB	02/11/04	35,194		This patch is included in 007 patch file	
	PCMCIA Patch for Cisco PCM352 card					
	PcmciaDTX10&DT870.CAB	08/02/04	60,309	Ver.1.01 Released		Do not need
	NetUI RF driver for WL1100C-CF RF card (Ambicom)					
	DTX10NETUI101.ARMV4T.CAB	03/11/04	148,381	Ver.1.01 Released		Do not need
Tools						
	Agency ID setting tool					
	UpdateUID.exe	03/31/03	7,680		Ver.1.00 Released	
	IE with Full Screen					
	BROWSER.exe	01/08/04	111,616		This tool is included in 007 patch file	

Note

- : Latest update or new release file information
 : Before updated file information

Important Note for each model patch and SP installation

For DT-X10M30E/ M30U model you need ...

- 1) ServicePackDTX10.CAB
- 2) PatchDTX10.007.CAB
- 3) PcmciaDTX10&DT870.CAB (If you use CISCO 352 PCMCIA card)
- 4) DTX10NETUI101.ARMV4T.CAB (If you use Ambicom WL1100C-CF RF card)

For DT-X10M30RC/ M30URC model you need ...

- 1) ServicePackDTX10.CAB
- 2) PatchDTX10.007.CAB
- 3) netuiDTX10.CAB

For DT-X10M30RC2/ M30URC2 model you need ...

- 1) ServicePackDTX10.CAB
- 2) PatchDTX10.007.CAB
- 3) wlan-GWCFDTX10.CAB

	File Name	Date	Size	DT-X10	DT-X10	DT-X10
		(mm/dd/yy)	(byte)	M30E/ M30U	M30RC/ M30URC	M30RC2/ M30URC2
RF module					Intel	Toyota
OS				4139	4139	4139
eVC++4.0						
	System library					
	CibSys.dll	03/01/05	13,824			
	CibSys.h	02/15/05	4,375		Ver.1.02 Released	
	CibSys.lib	03/01/05	48,558			
	KBDDTX10.100.CAB	03/11/05	115,327		Ver.1.00 Released This patch is included in 007 patch file	
	CMOS library					
	oemDecodeCE.dll	11/18/03	381,952			
	TDdecodece.dll	12/01/03	34,816		Ver.1.01 Released	
	TDdecodece.h	11/17/03	27,079			
	TDdecodece.lib	12/01/03	24,038			
	Laser library					
	LCUDRV.dll	03/07/05	28,160			
	LCUDRV.lib	07/28/05	21,126		Do not need	
	OBRREQ.h	08/03/05	18,973			
	LaserDTX10L.102.CAB	03/11/05	189,945			
	BT library					
	BTLib.dll	03/17/03	18,432			
	BTLib.h	03/17/03	8,903		Ver.1.00 Released	
	BTLib.lib	03/17/03	6,242			
	BTLib100.reg	03/17/03	375			
	Jpeg library					
	JpegCe.dll	03/17/03	109,568			
	JpegCe.h	03/17/03	1,035		Ver.1.00 Released	
	JpegCe.lib	03/17/03	2,666			
DotNetLibrary						
	System library					
	DirectCib.dll	03/01/05	9,216			
	CibSysCs.dll	03/23/05	15,360		Ver.1.02 Released	
	CibSysVB.dll	03/23/05	10,752			
	KBDDTX10.100.CAB	03/11/05	115,327		Ver.1.00 Released This patch is included in 007 patch file	
	CMOS library					
	TDdecodeceCs.dll	03/09/03	53,248			
	TDdecodeceVB.dll	03/09/03	36,864		Ver.1.00 Released	
	Laser library					
	LCUDRVCS.dll	06/02/05	36,864			
	LCUDRVVB.dll	03/23/05	28,672		Do not need	
	LaserDTX10L.102.CAB	03/11/05	189,945			
	BT library					
	BTLibCs.dll	03/09/03	16,896			
	SerialFuncCs.dll	08/24/04	11,776		Ver.1.01 Released	
	BTlibVB.dll	03/09/03	16,896			
	SerialFuncVB.dll	03/09/03	13,312			

Note

 : Latest update or new release file information
 : Before updated file information