

	File Name	Date	Size	DT-X10	DT-X10	DT-X10
		(mm/dd/yy)	(byte)	M10E	M10RC	M10RC2
RF module					Intel	Toyota
OS				4149	4149	4149
SDK						
	Export SDK					
	DT-X10 SDK.msi	03/17/03	28,063,744		Ver.1.00 Released	
	Emulation SDK					
	DT-X10(Laser)EM SDKforEVC.msi	12/04/03	46,293,504		Ver.1.00 Released	
Patch						
	General Patch					
	PatchDTX10L.004.CAB	01/28/05	129,591		2004/06/29 Released	
	PatchDTX10L.005.CAB	01/28/05	83,954			
	PatchDTX10L.007.CAB	08/06/05	1,028,977		Ver.007 Released (2005/8/12)	
	Toyota RF driver Patch					
	wlan-GWCFDTX10L.CAB	05/26/05	423,120		Do not need	Ver.1.00 Released (2005/8/12)
	Wireless LAN improvement Patch					
	netuiDTX10L.CAB	08/27/04	160,695	Do not need	Ver.1.03 Released	Do not need
	ActiveSync improvement Patch					
	BirdaDTX10&DT870&IT500&DT5100.CAB	02/11/04	35,194		This patch is included in 007 patch file	
	Laser Scanner improvement Patch					
	LaserDTX10.CAB	06/18/04	67,985		This patch is included in 007 patch file	
	PCMCIA Patch for Cisco PCM352 card					
	PcmciaDTX10&DT870.CAB	08/02/04	60,309	Ver.1.01 Released		Do not need
	NetUI RF driver for WL1100C-CF RF card (Ambicom)					
	DTX10NETUI101.ARMV4T.CAB	03/11/04	148,381	Ver.1.01 Released		Do not need
Tools						
	Agency ID setting tool					
	UpdateUID.exe	03/31/03	7,680		Ver.1.00 Released	
	IE with Full Screen					
	BROWSER.exe	01/08/04	111,616		This tool is included in 007 patch file	

Note

- : Latest update or new release file information
 : Before updated file information

Important Note for each model patch and SP installation

For DT-X10M10E model you need ...
1) PatchDTX10L.007.CAB 2) PcmciaDTX10&DT870.CAB (If you use CISCO 352 PCMCIA card) 3) DTX10NETUI101.ARMV4T.CAB (If you use Ambicom WL1100C-CF RF card)
For DT-X10M10RC model you need ...
1) PatchDTX10L.007.CAB 2) netuiDTX10L.CAB
For DT-X10M10RC2 model you need ...
1) PatchDTX10L.007.CAB 2) wlan-GWCFDTX10L.CAB

	File Name	Date	Size	DT-X10	DT-X10	DT-X10
		(mm/dd/yy)	(byte)	M10E	M10RC	M10RC2
RF module					Intel	Toyota
OS				4149	4149	4149
eVC++4.0						
	System library					
	ClbSys.dll	03/01/05	13,824	Ver.1.02 Released		
	ClbSys.h	02/15/05	4,375			
	ClbSys.lib	03/01/05	48,558			
	KBDDTX10.100.CAB	03/11/05	115,327	Ver.1.00 Released This patch is included in 007 patch file		
	CMOS library					
	oemDecodeCE.dll	11/18/03	381,952	Do not need		
	TDdecece.dll	12/01/03	34,816			
	TDdecece.h	11/17/03	27,079			
	TDdecece.lib	12/01/03	24,038			
	Laser library					
	LCUDRV.dll	03/07/05	28,160	Ver.1.03 Released		
	LCUDRV.lib	07/28/05	21,126			
	OBRREQ.h	08/03/05	18,973			
	LaserDTX10L.102.CAB	03/11/05	189,045	Ver.1.02 Released This patch is included in 007 patch file		
	BT library					
	BTLib.dll	03/17/03	18,432	Ver.1.00 Released		
	BTLib.h	03/17/03	8,903			
	BTLib.lib	03/17/03	6,242			
	BTLib100.req	03/17/03	375			
	Jpeg library					
	JpegCe.dll	03/17/03	109,568	Ver.1.00 Released		
	JpegCe.h	03/17/03	1,035			
	JpegCe.lib	03/17/03	2,666			
	DotNetLibrary					
	System library					
	DirectClb.dll	03/01/05	9,216	Ver.1.02 Released		
	ClbSysCs.dll	03/23/05	15,360			
	ClbSysVB.dll	03/23/05	10,752			
	KBDDTX10.100.CAB	03/11/05	115,327	Ver.1.00 Released This patch is included in 007 patch file		
	CMOS library					
	TDdececeCs.dll	03/09/03	53,248	Do not need		
	TDdececeVB.dll	03/09/03	36,864			
	Laser library					
	LCUDRVCS.dll	06/02/05	36,864	Ver.1.02 Released		
	LCUDRVVB.dll	03/23/05	28,672			
	LaserDTX10L.102.CAB	03/11/05	189,045	Ver.1.02 Released This patch is included in 007 patch file		
	BT library					
	BTLibCs.dll	03/09/03	16,896	Ver.1.01 Released		
	SerialFuncCs.dll	08/24/04	11,776			
	BTlibVB.dll	03/09/03	16,896			
	SerialFuncVB.dll	03/09/03	13,312			

Note

 : Latest update or new release file information
 : Before updated file information